## **ADVISORY BULLETIN # 16254**

JULY 18, 2016

SUBJECT: Deck Support Arm Change

MODELS AFFECTED: All MH24d, MH25, and MH27i Models Prior to S/N 16-139211

PURPOSE: Walker has found the rear dolly wheels of the DR64 are lifting off the ground when the deck is in the tilt-up position, which is transfering additional weight to the deck support arms. The deck support arms have been redesigned to increase travel, enabling the rear dolly wheels to support the weight of the deck when in the tilt-up position. The new deck support arms (RH P/N 2430-2, LH P/N 2431-2) supersede the original design (RH P/N 2430, LH P/N 2431) and can be used as a replacement part on all earlier MH tractors; It is recommended to change both arms as a pair.

## PARTS REQUIRED:

Order one (1) 2430-2 Deck Support Arm RH and one (1) 2431-2 Deck Support Arm LH.



